

## INSTALL INSTRUCTIONS C-TCB-LOCK TELESCOPING COMPUTER BASE LOCK

## **TOOLS REQUIRED:**

(2) <sup>1</sup>/<sub>2</sub>" Combination Wrench3/16" Allen Wrench

7/16" Combination Wrench Phillips Screw Driver

## MATERIAL LIST:

ITEM	<u>QTY</u>	<b>DESCRIPTION</b>	
11.4	1	а·т 1	


#1 1 Spring Lock


#2 1 Adjustable Locking Disc

## HARDWARE:

ITEM	<u>QTY</u>	DESCRIPTION
#3	1	<sup>1</sup> / <sub>4</sub> -20 x <sup>3</sup> / <sub>4</sub> " Pan head Machine Screw
#4	1	<sup>1</sup> /4-20 Nylock Nut

Confirm receipt of all hardware and components.





Consolidator<sup>®</sup> • Kwik-Raze<sup>®</sup> • Collins Dynamics<sup>®</sup> • Kwik-Kit<sup>™</sup> PrisonerTransports • K-9Transports 75 Jacksonville Rd • P.O. Box 2099 • Warminster, PA 18974 • 800.524.9900 / 215.957.0720(P) • 215.957.0729 (F) www.Havis.com